

2008 Chevrolet Impala VIN: 2G1WB55K181000000 Inspection Date: November 06, 2015

Exterior	2
Glass	3
Tires and Wheels	3
Underbody	4
Underhood	4
Interior	4
Electrical System	5
Road Test Findings	5





Inspection Information

Inspection Date: 2015-11-06 Model: Impala Body Style: Sedan Drive Type: FWD Exterior Color: Silver Year: 2008 Mileage: 128000 Transmission: Standard Inspector: Adam Singer Door Count: 4 Make: Chevrolet VIN: 2G1WB55K181000000 Engine: 6 cylinder Interior Color: Gray

 ${\sf G}={\sf Good}$ - This item is in good condition and/or is performing to standard.

 ${\sf F}={\sf Fair}$ - This item is in fair condition and/or is performing adequately.

P = Poor - This item is in poor condition and/or is performing below standard.

Exterior

- 1. Hood
- 2. Front
- 3. Front Bumper Dents, cracks or scratches present
- 4. Fenders
- 5. Doors
- 6. Roof Several scratches present
- 7. Rear
- 8. Rear Bumper
- 9. Trunk
- 10. Trim
- 11. Fuel Door
- 12. Paint Condition



Glass

G	F	Ρ

- 13. Windshield
- 14. Windows
- 15. Mirrors Some paint missing
- 16. Rear Window

Mirrors



Tires and Wheels

G	F	Ρ

17. Condition of Tires

- 18. Condition of Wheels Hubcap needs replaced
- 19. Spare Tire

Condition of Wheels Condition of Wheels





nspect aride

Underbody

- 20. Frame
- 21. Exhaust System
- 22. Transmission
- 23. Drive Axle
- 24. Suspension
- 25. Brake System Brakes squeak

Underhood

- - 26. Engine Compartment
 - 27. Battery Excessive corrosion present
 - 28. Oil
 - 29. Fluids
 - 30. Wiring
 - 31. Belts
 - 32. Hoses
 - 33. Any Non-Stock Modifications

Interior

G	F	Ρ

- 34. Seats
- 35. Headliner
- 36. Carpet
- 37. Door Panels
- 38. Glove Box
- 39. Vanity Mirrors
- 40. Interior Trim
- 41. Dashboard
- 42. Dashboard Gauges



- 43. Air Conditioning
 - 44. Heater
 - 45. Defroster Rear defrost not functional

Electrical System

G	F	Р

G

- 46. Power Locks
- 47. Power Seats
- 48. Power Steering
- 49. Power Windows
- 50. Power Mirrors
- 51. Audio System
- 52. Onboard Computer
- 53. Headlights
- 54. Taillights
- 55. Signal Lights
- 56. Brake Lights
- 57. Parking Lights

Road Test Findings

- 58. Starting
 - 59. Idling
 - 60. Engine Performance
 - 61. Acceleration
 - 62. Transmission Shift Quality
 - 63. Steering
 - 64. Braking
 - 65. Suspension Performance

		01.	Dianity
1		65.	Susper



Pictures







Summary

Poor

Exterior Front Bumper - Dents, cracks or scratches present Tires and Wheels Condition of Wheels - Hubcap needs replaced Underhood Battery - Excessive corrosion present