

Inspection Information

Inspection Date: 2015-11-06
Model: Impala
Body Style: Sedan
Drive Type: FWD
Exterior Color: Silver

Year: 2008
Mileage: 128000
Transmission: Standard
Inspector: Adam Singer
Door Count: 4

Make: Chevrolet
VIN: 2G1WB55K181000000
Engine: 6 cylinder
Interior Color: Gray

G = Good F = Fair P = Poor

G F P

Exterior

- 1. Hood
- 2. Front
- 3. Front Bumper
- 4. Fenders
- 5. Doors
- 6. Roof
- 7. Rear
- 8. Rear Bumper
- 9. Trunk
- 10. Trim
- 11. Fuel Door
- 12. Paint Condition

Glass

- 13. Windshield
- 14. Windows
- 15. Mirrors
- 16. Rear Window

Tires and Wheels

- 17. Condition of Tires
- 18. Condition of Wheels
- 19. Spare Tire

Underbody

- 20. Frame
- 21. Exhaust System
- 22. Transmission

G F P

Underbody

- 23. Drive Axle
- 24. Suspension
- 25. Brake System

Underhood

- 26. Engine Compartment
- 27. Battery
- 28. Oil
- 29. Fluids
- 30. Wiring
- 31. Belts
- 32. Hoses
- 33. Any Non-Stock Modifications

Interior

- 34. Seats
- 35. Headliner
- 36. Carpet
- 37. Door Panels
- 38. Glove Box
- 39. Vanity Mirrors
- 40. Interior Trim
- 41. Dashboard
- 42. Dashboard Gauges
- 43. Air Conditioning
- 44. Heater
- 45. Defroster

G F P

Electrical System

- 46. Power Locks
- 47. Power Seats
- 48. Power Steering
- 49. Power Windows
- 50. Power Mirrors
- 51. Audio System
- 52. Onboard Computer
- 53. Headlights
- 54. Taillights
- 55. Signal Lights
- 56. Brake Lights
- 57. Parking Lights

Road Test Findings

- 58. Starting
- 59. Idling
- 60. Engine Performance
- 61. Acceleration
- 62. Transmission Shift Quality
- 63. Steering
- 64. Braking
- 65. Suspension Performance

Comments

- 3. Front Bumper Dents, cracks or scratches present
- 6. Roof Several scratches present
- 15. Mirrors Some paint missing
- 18. Condition of Wheels Hubcap needs replaced
- 25. Brake System Brakes squeak
- 27. Battery Excessive corrosion present
- 45. Defroster Rear defrost not functional

Pictures



